

Table 10

**Finding of Suitability to Transfer
First CERFA Parcel Transfer
Radon Testing Results
Fort McClellan, Alabama**

Building No	Results pCi/L	Date Tested	Area Tested	Mitigated Date	Post-mitigation Results	Date test Completed
141	9.0, 10.6, 4.2 15.4, 4.3, 4.5	1/27/89 - 4/17/90 1/27/94 – 2/6/95	Basement	December-96	Results ranged from 0.3 – 1.0 in monitors placed in 8 locations	11/19/98